

Form Approved
OMB No. 2010-0019
Approval Expires 12-31-89

2 Www.

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Comprehensive Assessment Information Rule REPORTING FORM

90-93000006



when completed, send this form to:	For Agency Use Only:
Document Processing Center	Date of Receipt:
Office of Toxic Substances, TS-790 J.S. Environmental Protection Agency 401 M Street, SW	Document Control Number:
Washington, DC 20460 Attention: CAIR Reporting Office	Docket Number:

Have you submitted a completed separate form for each substance you are required to report on? Have you submitted a completed separate form for each site at which you manufacture, import, or process a listed substance? For each listed substance you must report on, have you reported on all activities you engage in at each site using the listed substance on the same reporting form? If you are claiming information as Confidential Business Information (CBI), have you completed the CBI substantiation form in Appendix II of the form for each category containing CBI? Failure to submit a completed CBI substantiation form with a reporting form containing CBI will result in the waiver of your claim of confidentiality. For each question that you are required to answer, have you responded by either providing the data, stating not applicable ("N/A"), or, if the question permits, stating unknown ("UK")? Have you right justified your responses to questions asked that require respondents to give a numeric response in a series of boxes (e.g., the answer "372" is entered as [0][0][3][7][2])? 10. Have your responses been given in alpha, numeric or alpha-numeric form such as 3 million or 3,000,000? Responses must not be given in scientific notation such as 3 x 106. 11. If you needed additional space to report the required data, have you checked the continuation sheet box at the bottom of each page that requires additional space; attached additional copies of the specific

questions of this form that contain additional information; and listed the attachments in Appendix I of the reporting form?

1.03	Does the in the ab	substance you are reporting on have an "x/p" designation associated with it ove-listed Federal Register Notice?
<u>CBI</u>	Ŷes)	
[_]		
	110	
	under	u manufacture, import, or process the listed substance and distribute it a trade name(s) different than that listed in the Federal Register Notice? e the appropriate response.
CBI	Yes .	
[_]	No).	
	_	the appropriate box below:
	\bowtie	You have chosen to notify your customers of their reporting obligations
		Provide the trade name(s) Solithane 113
		(Morton Thickol)
	[-]	You have chosen to report for your customers
	[_]	You have submitted the trade name(s) to EPA one day after the effective
	·1	date of the rule in the <u>Federal Register</u> Notice under which you are reporting.
1.05 CBI	reporting	a trade name product and are reporting because you were notified of your requirements by your trade name supplier, provide that trade name.
[]	Is the tra	de name product a mixture? Circle the appropriate response.
(Ŷes)	
	No	
1.06 CBI	Certificat sign the c	ion The person who is responsible for the completion of this form must ertification statement below:
	"I hereby entered on	certify that, to the best of my knowledge and belief, all information this form is complete and accurate."
	Tamela	S. Bailey Parish & Karley 12/2/92 NAME SIGNATURE DATE SIGNED
	Senior Inc	Lustrial Nypierist (609) 490 - 6861 (update from TITLE NO. 9/10/89
[_]	Mark (X) th	is box if you attach a continuation sheet.
	7 4 4	Oction 1: 4
116	pad 1	Reviewed: " 12/6/92
•	615	1 Kfarrell 12/6/92
	1 W	

11	Parent Company Identification	
<u>I</u>	Name [G] E N] E R A L E L E C T R L C G M P A N Y Address [3] 13 5 E A S T Q N T U R N P L K E	
	(EIAILIRIEILIEILIDILILILILILILILILILILILILILILIL]1
	$\begin{bmatrix} \boxed{C} \boxed{T} \end{bmatrix}$ $\begin{bmatrix} \boxed{O} \boxed{6} \boxed{4} \boxed{3} \boxed{1} \boxed{1} \end{bmatrix}$]_ _
	Dun & Bradstreet Number [진]진]-[][][[][[]][[]][[]][[]][[]][[]][[]	<u> </u>
. 12	Prechnical Contact	. — . –
BI		·'-'- · _! _!
_1		·'-'- - -
	Address PIGITIBIOIXITIPIODITIPIET Street	
	[<u>지</u>] [[[[집] 5 년] 3] [집] 3	1013
	Telephone Number[조1 <u>页</u>] - (포1 <u>页</u>) - (포1 <u></u> - (Σ1 <u></u>) - (Σ1 <u></u>) - (Σ1 <u></u>) - (Σ1	
.13	3 This reporting year is from [진] [중]중] to [기고,	$\frac{8}{8}$

1.14	Facility Acquired If you purchased this facility during the reporting year, provide the following information about the seller:
CBI	Name of Seller [_]_]_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_][_]_]_]_]
	Employer ID Number
	Date of Sale
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
1.15	Facility Sold If you sold this facility during the reporting year, provide the following information about the buyer:
<u>CBI</u>	Name of Buyer []]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	(_ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _
	[_]_] [_]_]_]_]_]_]-[_]_]_]_]
	Employer ID Number
	Date of Purchase
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
[_]	Mark (X) this box if you attach a continuation sheet.

DAPT C	TOENTIFICATION	OF	MIXTURES
--------	----------------	----	----------

1.17 Mixture -- If the listed substance on which you are required to report is a mixture or a component of a mixture, provide the following information for each component chemical. (If the mixture composition is variable, report an average percentage of each component chemical for all formulations.)

CBI

Component Name	Supplier Name	Averag Composition (specify pr e.g., 45)	by Weight recision,
2,4 Toluene Diisocyar	nate Morton Thiokol	6.5	.5
Isocyanate terminated po	olylol Morton Thiokol	93.5	. 5
NA	NA.	NA.	
NA	N A	NANA	
N A	N A	N A	
NA	NA .	Total NA	100%

^[] Mark (X) this box if you attach a continuation sheet.

2.04	State the quantity of the listed substance that your facility manufactured, imported or processed during the 3 corporate fiscal years preceding the reporting year in descending order.
CBI	
[_]	Year ending $[\overline{1}]\overline{2}$ $[\overline{8}]\overline{7}$ Mo. Year
	Quantity manufactured NA kg
	Quantity imported NA kg
	Quantity processed
	Year ending $[\overline{1}]\overline{2}$ $[\overline{8}]\overline{6}$ Mo. Year
	Quantity manufactured NA k
	Quantity imported
	Quantity processed
	Year ending $[\frac{1}{2}]$ $[\frac{8}{5}]$ Mo. Year
	Quantity manufactured
	Quantity imported
	Quantity processed
2.05 CBI	Specify the manner in which you manufactured the listed substance. Circle all appropriate process types.
[_]	11/A
	Continuous process
	Semicontinuous process
	Batch process
[_]	Mark (X) this box if you attach a continuation sheet.

2.09	listed substanc substance durin	argest volume manufacturing or processing proce e, specify the number of days you manufactured g the reporting year. Also specify the average s type was operated. (If only one or two opera	or processed number of h	the listed
<u>CBI</u>			Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)		
		Manufactured	NA	NA
		Processed	260	1.5-2.0
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		
		Manufactured	<u>NA</u>	NA
		Processed	_NA	NA
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		
		Manufactured	NA	NA
		Processed	NA	NA
2.10 CBI	substance that we chemical. Maximum daily in	am daily inventory and average monthly inventory was stored on-site during the reporting year in the experimental experime	the form of	
	Mark (X) this ho	ox if you attach a continuation sheet.		·

_]	a.	further explanation and b. % of Quantity	c.	d.
	Product Types ¹	Manufactured, Imported, or Processed	% of Quantity Used Captively On-Site	Type of End-User
	K	100%	100%	CM
	NA	NA	NA	NA
	NA	NA	NA	NA
	NA	NA	NA	NA
	NA	NA	NA	NA
	NA	NA	NA	NA
	<pre>B = Synthetic reactar C = Catalyst/Initiate Sensitizer</pre>	nt . Properties .	<pre>1 = Plasticizer N = Dye/Pigment/Colo D = Photographic/Rep</pre>	orant/Ink and addit
*	<pre>C = Catalyst/Initiate Sensitizer D = Inhibitor/Stabil Antioxidant E = Analytical reage: F = Chelator/Coagulat G = Cleanser/Deterge: H = Lubricant/Fricti agent I = Surfactant/Emuls J = Flame retardant K = Coating/Binder/A</pre>	nt or/Accelerator/ izer/Scavenger/ nt ot/Sequestrant ont/Degreaser on modifier/Antiwear	<pre>M = Plasticizer N = Dye/Pigment/Colo D = Photographic/Rep and additives P = Electrodeposition C = Fuel and fuel act Explosive chemic S = Fragrance/Flavor T = Pollution control U = Functional fluid W = Metal alloy and W = Rheological mod X = Other (specify)</pre> ype of end-users:	orographic chemical on/Plating chemical dditives cals and additives chemicals of chemicals dis and additives additives ifier

a.	b. N	c.	nce remouns d.
Product Type ¹	Final Product's Physical Form ²	Average % Composition of Listed Substance in Final Product	Type of End-Users
NA	<u>NA</u>	NA	NA
NA	NA	NA	NA
NA	NA	NA	NA
NA	NA	NA	NA
NA	AM	NA	NA
agent	ator/Accelerator/ dlizer/Scavenger/ gent lant/Sequestrant gent/Degreaser dion modifier/Antiwear	<pre>M = Plasticizer N = Dye/Pigment/Color 0 = Photographic/Repr and additives P = Electrodeposition Q = Fuel and fuel add R = Explosive chemica S = Fragrance/Flavor T = Pollution control U = Functional fluids</pre>	ographic chemical Plating chemical itives als and additives chemicals chemicals and additives
C = Catalyst/Initia Sensitizer D = Inhibitor/Stabs Antioxidant E = Analytical reag F = Chelator/Coagul G = Cleanser/Deterg H = Lubricant/Frict agent I = Surfactant/Emul J = Flame retardant K = Coating/Binder/ 2 Use the following of	ator/Accelerator/ ilizer/Scavenger/ gent lant/Sequestrant gent/Degreaser tion modifier/Antiwear sifier Adhesive and additive	<pre>M = Plasticizer N = Dye/Pigment/Color 0 = Photographic/Repr and additives P = Electrodeposition Q = Fuel and fuel add R = Explosive chemica S = Fragrance/Flavor T = Pollution control U = Functional fluids V = Metal alloy and a W = Rheological modif es X = Other (specify) final product's physic</pre>	rant/Ink and additional control contro
C = Catalyst/Initia Sensitizer D = Inhibitor/Stabs Antioxidant E = Analytical reag F = Chelator/Coagul G = Cleanser/Deterg H = Lubricant/Frict agent I = Surfactant/Emul J = Flame retardant K = Coating/Binder/ 2 Use the following of A = Gas B = Liquid C = Aqueous solution D = Paste	ator/Accelerator/ ilizer/Scavenger/ gent lant/Sequestrant gent/Degreaser lion modifier/Antiwear sifier Adhesive and additive codes to designate the F2 = Cry F3 = Gra F4 = Oth G = Gel	M = Plasticizer N = Dye/Pigment/Color O = Photographic/Repr and additives P = Electrodeposition Q = Fuel and fuel add R = Explosive chemica S = Fragrance/Flavor T = Pollution control U = Functional fluids V = Metal alloy and a W = Rheological modif s X = Other (specify) final product's physic stalline solid nules er solid	rant/Ink and additional control contro
C = Catalyst/Initia Sensitizer D = Inhibitor/Stabs Antioxidant E = Analytical reag F = Chelator/Coagul G = Cleanser/Deterg H = Lubricant/Frict agent I = Surfactant/Emul J = Flame retardant K = Coating/Binder/ 2 Use the following of A = Gas B = Liquid C = Aqueous solution D = Paste E = Slurry F1 = Powder	ator/Accelerator/ ilizer/Scavenger/ gent lant/Sequestrant gent/Degreaser lion modifier/Antiwear sifier Adhesive and additive codes to designate the F2 = Cry F3 = Gra F4 = Oth G = Gel H = Oth	M = Plasticizer N = Dye/Pigment/Color 0 = Photographic/Repr and additives P = Electrodeposition Q = Fuel and fuel add R = Explosive chemica S = Fragrance/Flavor T = Pollution control U = Functional fluids V = Metal alloy and a W = Rheological modif s X = Other (specify) final product's physic stalline solid nules er solid er (specify)	rant/Ink and additional control contro
C = Catalyst/Initia Sensitizer D = Inhibitor/Stabs Antioxidant E = Analytical reag F = Chelator/Coagul G = Cleanser/Deterg H = Lubricant/Frict agent I = Surfactant/Emul J = Flame retardant K = Coating/Binder/ 2 Use the following of A = Gas B = Liquid C = Aqueous solution D = Paste E = Slurry F1 = Powder	ator/Accelerator/ ilizer/Scavenger/ gent lant/Sequestrant gent/Degreaser lion modifier/Antiwear sifier Adhesive and additive codes to designate the F2 = Cry F3 = Gra F4 = Oth G = Gel H = Oth odes to designate the	M = Plasticizer N = Dye/Pigment/Color 0 = Photographic/Repr and additives P = Electrodeposition Q = Fuel and fuel add R = Explosive chemica S = Fragrance/Flavor T = Pollution control U = Functional fluids V = Metal alloy and a W = Rheological modif s X = Other (specify) final product's physic stalline solid nules er solid er (specify)	rant/Ink and additional control contro

_1						NΔ	<u> </u>	٠. جريا
_	In bulk						•	
•	As a mixture					Less Tha		kg/;
	In articles	• • • • • • • • •		• • • • • • • •		- NA		Kg ;
					•			
	•							
		٠.						
			•					
		•						
	•							

3.03 CBI	a.	Circle all applicable containers used to transport the listed substance to your facility.
		Bags 1
		Boxes 2
		Free standing tank cylinders 3
		Tank rail cars 4
		Hopper cars 5
		Tank trucks 6
		Hopper trucks 7
		Drums 8
		Pipeline 9
		Other (specify) @1 gallon can
	þ.	If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.
		Tank cylinders
		Tank rail cars
		Tank trucks

BI reporting year in the fo	e listed substance used as a room of a class I chemical, class by weight, of the listed subs	ss II chemical, or polymer, an
	Quantity Used (kg/yr)	<pre>% Composition by Weight of Listed Sub stance in Raw Materia (specify ± % precision</pre>
Class I chemical	47.67	6-7% ±1
	NA	NA
	NA	NA
Class II chemical	NA	<i>NA</i>
	AM	NA
	NA	NA
Polymer	NA	<i>NA</i>
	NA	NA
	M	NA
		•

4.03	Submit a copy or reasonable facsimile of any hazard information (other than an MSDS) that is provided to your customers/users regarding the listed substance or any formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.									
	Yes				• • • • • • • • • • • •	1				
	No			·		(2				
4.04 CBI	For each activity that uses to corresponding to each physical listed. Physical states for the time you import or begin manufacturing, storage, dispose	al state of the importing and to process the	listed subs processing a listed subs	stance duri: activities a stance. Phy	ng the activit are determined ysical states	y lat for				
[_]	final state of the product.		Phys	sical State						
_	final state of the product.	 Solid	Phys Slurry	sical State	Liquified Gas	Gas				
_		Solid	•			Gas 5				
_	final state of the product. Activity		Slurry	Liquid	Gas					
_	Activity Manufacture	1	Slurry 2	Liquid 3	Gas 4	5				
_	Activity Manufacture Import	1	Slurry 2 2	Liquid 3 3	Gas 4 4	5				
_	Activity Manufacture Import Process	1	Slurry 2 2 2 2	Liquid 3 3	Gas 4 4 4	5 5 5				

	Mark	(X)	this	box	if	you	attach	а	cont	inuati	ion	sheet	٠.
--	------	-----	------	-----	----	-----	--------	---	------	--------	-----	-------	----

4.06	For each physical state of the listed substance, specify the corresponding flashpoint, and the test method used to derive the flashpoint value.
	Solid N/A
	Flashpoint
	Test method
	Liquid
	Flashpoint
	Test method
	<u>Gas/Vapor</u>
	Flashpoint
	Test method
	Yes
.07	Indicate the temperature at which the listed substance undergoes autopolymerization or autodecomposition. See MSDS
	Autopolymerizes at
	Autodecomposes at
	Indicate if hazard information/MSDS has been submitted in lieu of response by circling the appropriate response.
	Yes
	No

	Product T	ypes Co	ntainin	g the I	Listed S	Subs
Extinguishing Media	1	2	3	4	5	_
Vater	_NA_	_NA_	_NA_	_NA_	NA_	_1
Foam	_NA_	<u>NA</u>	NA_	_NA_	NA	_1
co,	<u>NA</u>	<u>NA</u>	<u>NA</u>	NA_	<u>NA</u>	N
Dry chemical (e.g., sodium bicarbonate)	NA_	NA	_NA_	_NA_	_NA_	_7
Halogenated hydrocarbon (e.g., carbon tetrachloride, methyl bromide)	_NA	NA_	NA_	<u>NA</u>	<u>NA</u>	_N
Other (specify)	NA	NA	<u>NA</u>	<u>NA</u>	<u>NA</u>	
No						
No Identify the product types listed under		lumn (1		the fol	llowing	
No		lumn (1	l-6) in	the fol	llowing	
No Identify the product types listed under Product Type No.		lumn (1	-6) in	the fol	llowing	
No Identify the product types listed under Product Type No. 1 .		lumn (1 Pro	-6) in	the fol	llowing	
No Identify the product types listed under Product Type No. 1 . 2		lumn (1 Pro	-6) in	the fol	llowing	
No Identify the product types listed under Product Type No. 1 . 2		lumn (1 Pro	d-6) in	the fol	llowing	
No Identify the product types listed under Product Type No. 1 . 2 . 3 .		lumn (1 Pro NA NA NA	a-6) in	the fol	llowing	
No Identify the product types listed under Product Type No. 1 . 2 . 3 . 4 . 5		lumn (1 Pro NA NA NA NA	a-6) in	the fol	llowing	
No Identify the product types listed under Product Type No. 1 . 2 . 3 . 4 . 5		lumn (1 Pro NA NA NA NA	a-6) in	the fol	llowing	

	CAS No.	Name	Reaction (specify)
	NA	NA	NA
	NA NA	NA	NA
	NA	NA NA	NA
	NA	NA NA	NA NA
	response by	hazard information/MSDS has be circling the appropriate respo	onse.
	<u></u>		
	No	• • • • • • • • • • • • • • • • • • • •	
			of autoxidation? Circle the
4.12	Autoxidation I appropriate respo	s the listed substance capable nse.	OI autoxidation. Ollele tue
	Yes		•••••
	No		
	No		
	No	hazard information/MSDS has be	een submitted in lieu of
	No	hazard information/MSDS has be	een submitted in lieu of
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of onse.
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of onse.
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of onse.
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of onse.
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of onse.
	No	hazard information/MSDS has be circling the appropriate response	een submitted in lieu of onse.

Name of Additive	Inhibit or <u>Stabiliz</u>	Added	(specify
NA	NA	NA	NA
NA	NA	NA	NA
NA NA	NA	NA	NA
Indicate if hazard in response by circling	the appropriate respo	nse.	
Yes/			
No			• • • • • • • • • • • • • • • • • • • •
Use the following codes t I = Inhibitor S = Stabilizer	o designate inhibitor	and stabilizer:	
I = Inhibitor	o designate inhibitor	and stabilizer:	
I = Inhibitor	o designate inhibitor	and stabilizer:	
I = Inhibitor	o designate inhibitor	and stabilizer:	
I = Inhibitor	o designate inhibitor	and stabilizer:	
I = Inhibitor	o designate inhibitor	and stabilizer:	
I = Inhibitor	o designate inhibitor	and stabilizer:	
I = Inhibitor S = Stabilizer		and stabilizer:	
I = Inhibitor S = Stabilizer		and stabilizer:	
I = Inhibitor S = Stabilizer			
I = Inhibitor S = Stabilizer			

[] Mark (X) this box if you attach a continuation sheet.

PART	в Р	ARTITION COEFFICIENTS					
5.02	a.	Specify the half-life	of the listed sub	stance in the following	g med	iia.	
		Media		Half-life (specif	y uni	lts)	
		Groundwater	_IJK				
		Atmosphere	UK				
		Surface water	_UK				
		Soil	<u>UK</u>				
	ъ.	Identify the listed st life greater than 24	ubstance's known t hours.	ransformation products	that	t have a	half-
		CAS No.	Name	<pre>Half-life (specify units)</pre>		Med	<u>ia</u>
		UK	UK	UK	in _	IJK	
		UK	UK	UK	in	UK	
		UK	UK	UK	in	UK	
		UK	UK .	<u>UK</u>	in .	UK	
5.03	Spe	cify the octanol-water	partition coeffic	ient, K _{ow} <u>UK</u>			at /5°0
		hod of calculation or			· · · · · · · · · · · · · · · · · · ·		
5.04	Spe	cify the soil-water pa	rtition coefficien	ıt, K _a <u>UK</u>			at 25°0
	Soi	1 type	• • • • • • • • • • • • • • • • • • • •	<u>UK</u>			
5.05	Spe	cify the organic carbo	n-water partition	UK			at 25°0
5.06	Spe	cify the Henry's Law C	onstant, H	UК		at	-m³/mole


[] Mark (X) this box if you attach a continuation sheet.

	Company Tune Circle the number which most engagementally	
6.01	Company Type Circle the number which most appropriately	describes your company.
CBI	Corporation	
''	Sole proprietorship	•••••
	Partnership	•••••
	Other (specify)	•••••
6.02 CBI	At the end of the reporting year, were you constructing ad site that were not yet in operation at the end of the repo now being used or will be used in the future for manufactu processing the listed substance? Circle the appropriate r	rting year, but which are ring, importing, or
[_]	Yes	
	No	
<u>CBI</u>	List all of the product types that you manufacture that co as a raw material, and the percentage of the name-plate ca listed substance that each product type represents. The to percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance.	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed
6.03 <u>CBI</u>	List all of the product types that you manufacture that co as a raw material, and the percentage of the name-plate ca listed substance that each product type represents. The t percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the
<u>CBI</u>	List all of the product types that you manufacture that con as a raw material, and the percentage of the name-plate callisted substance that each product type represents. The transfer percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance.	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed
<u>CBI</u>	List all of the product types that you manufacture that con as a raw material, and the percentage of the name-plate callisted substance that each product type represents. The transfer percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance. Product Type	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed
<u>CBI</u>	List all of the product types that you manufacture that con as a raw material, and the percentage of the name-plate callisted substance that each product type represents. The transfer percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance. Product Type	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed
<u>CBI</u>	List all of the product types that you manufacture that con as a raw material, and the percentage of the name-plate callisted substance that each product type represents. The transfer percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance. Product Type	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed
<u>CBI</u>	List all of the product types that you manufacture that con as a raw material, and the percentage of the name-plate callisted substance that each product type represents. The transfer percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance. Product Type	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed
<u>CBI</u>	List all of the product types that you manufacture that con as a raw material, and the percentage of the name-plate callisted substance that each product type represents. The transfer percentiles should equal 100 percent. State the total name process type(s) used to manufacture all product types that substance. Product Type	ntain the listed substance pacity dedicated to the otal of all capacity e-plate capacity of the contain the listed

<u>_</u> 1	these costs, refer to the instructions.) Average Total Costs	N A	\$/k
٠	Importing Listed Substance is a small % of Mixton	NA ure NA	S/k S/k
	Average Variable Costs Manufacturing	NA NA	
	State your average purchase price of the listed substance, if	purchased as a	raw
.07 BI	material during the reporting year. % of Mixture represented by the listed substance	*	
BI	material during the reporting year.	*	
BI] .08 BI	material during the reporting year. % of Mixture represented by the listed substance Average purchase price State your company's total sales and sales of the listed substance the reporting year. No Material sold in bulk	* 1.32 tance sold in bu	\$/\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
BI] .08 BI	Material during the reporting year. % of Mixture represented by the listed substance Average purchase price	tance sold in bu	\$/\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
BI] 08	material during the reporting year. % of Mixture represented by the listed substance Average purchase price	* 1.32 tance sold in bu [] NA NA	\$71 ilk fo
.08 BI	Material during the reporting year. % of Mixture represented by the listed substance Average purchase price	* 1.32 tance sold in bu [] NA NA	\$/

6.09 CBI	State your company's total sales and sales of the listed substance the corporate fiscal year preceding the reporting year. (Refer to for question 6.08 for the methodology used to answer this question.	(He Instructions
	No Pull color of lighted material	NA
	Year ending	· [] [] [] Year
	Company's total sales (\$)	
	Sales of listed substance (\$)	NA
6.10 CBI	State your company's total sales and sales of the listed substance the 2 corporate fiscal years preceding the reporting year in descen (Refer to the instructions for question 6.08 for the methodology us question.)	ed to answer this
		NA — —
	Year ending	· [] [] [] [] [] []
	Company's total sales (\$)	N A
	Sales of listed substance (\$)	
	Year ending	· [_]_] [_] [_] Year
	Company's total sales (\$)	
	Sales of listed substance (\$)	NA NA

PROCESS FLOW CHART FOR QUESTION 7.01



	In accordance substance	rdance each o	with the of the th	e instruction hree major (g	ns, provide a greatest volu	separate me) proces	process bloss types in	ock flow di volving the	agram e listed
CBI					_				
	Process	type	• • • • • • •	Spacecras	ft urethane	e coating	mixture		
		•							
								-	
									•
									1

Operation Typical Operating Pressure ID Equipment Temperature Range Vess Number Type Range (°C) (mm Hg) Compos O	Unit	arame	coating mix	Operating	
OZ Syringe fair gun amb. amb. plasti NA	Operation ID	Equipment	Temperature	Pressure Range	Vesse Composi
NA NA NA NA NA NA	0	Bell Jar	10-30	559 ¥	Gloss
NA N	_02_	syringe lair gun	amb.	amb.	plastic
NA N	AA	NA	NA	M	
NA N	NA	A	NA	NA	NA
NA N		NA	NA	NA	NA
NA	<u> </u>			NA	
NA NA NA NA NA	<u> </u>	NA	<u>NA</u>	NA	
NA NA NA MA	<u>NA</u>	NA		NA	NA
				<u></u>	_NA_
*measured pressure draw of pump	<u>NA</u>	NA	NA	<u>NA</u>	AIX_
	NA	MA	NA		

[_]	Process ty	-		vating mat			
	Process Stream ID Code	Known Compounds ¹ Solithare 113 * Solithare 113-300* Additive package NA NA NA NA NA	Concentrations ^{2,3} (% or ppm) 10-50 EW 10-50 EW MA NA NA NA NA	other Expected Compounds NA NA NA NA NA NA NA NA NA N	Estimated Concentrations (% or ppm) NA NA NA NA NA NA NA NA NA N		
		NA NA NA NA	NA NA NA NA	NA NA NA NA	NA NA NA NA		
	continued 1 * CONTAI		Substance ostance				

SECTION 8 RESIDUAL TREATMENT GENERATION, CHARACTERIZATION, TRANSPORTATION, AND MANAGEMENT

General Instructions:

For questions 8.04-8.06, provide a separate response for each residual treatment block flow diagram provided in question 8.01, 8.02 or 8.03. Identify the process type from which the information is extracted.

For questions 8.05-8.33, the Stream Identification Codes are those process streams listed in either the Section 7 or Section 8 block flow diagrams which contain residuals for each applicable waste management method.


For questions 8.07-8.33, if residuals are combined before they are handled, list those Stream Identification Codes on the same line.

Questions 8.09-8.33 refer to the waste management activities involving the residuals identified in either the Section 7 or Section 8 block flow diagrams. Not all Stream Identification Codes used in the sample answers (e.g., for the incinerator questions) have corresponding process streams identified in the block flow diagram(s). These Stream Identification codes are for illustrative purposes only.

For questions 8.11-8.33, if you have provided the information requested on one of the EPA Office of Solid Waste surveys listed below within the three years prior to your reporting year, you may submit a copy or reasonable facsimile in lieu of answering those questions which the survey addresses. The applicable surveys are: (1) Hazardous Waste Treatment. Storage, Disposal, and Recycling Survey; (2) Hazardous Waste Generator Survey; or (3) Subtitle D Industrial Facility Mail Survey.

[_]	Mark	(X)	this	рох	if	you	attach	a	continuation	sheet.	

FLOW CHART FOR QUESTION 8.01



8.02	In accordance with the which describe each of question 7.02.	instructions, provide residual treat the treatment processes used for res	tment block flow diagram(s siduals identified in
CBI	•	a series and discrem & C	
[_]	Process type	See question and diagram 8.0	
		•	

8.04	residual treatment block flow diagram diagram is provided for more than one complete it separately for each process.	* •
	No on-site treatment of Process type	residual materials generated in this
	Unit Operation ID Number (as assigned in questions 8.01, 8.02, or 8.03)	Typical Equipment Type
	NA	NA
	NA	NA
	NA	NA.
	NA	NA
	NA	NA ·
	NA	NA
	NA	NA
		,

8.05 (continued)

1 Use the following codes to designate the type of hazardous waste:

I = Ignitable

C = Corrosive

R = Reactive

E = EP toxic

T = Toxic

H = Acutely hazardous

²Use the following codes to designate the physical state of the residual:

GC = Gas (condensible at ambient temperature and pressure)

GU = Gas (uncondensible at ambient temperature and pressure)

SO = Solid

SY = Sludge or slurry

AL = Aqueous liquid

OL = Organic liquid

IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

8.05 continued below

[] Mark (X) this box if you attach a continuation sheet.

(continued)

8.05

For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component Assign an additive package number to each additive package and list this number in column b. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentrations (% or ppm)			
1	Silicon Dioxide	8.0	EW	27	
	Dibutyltindilaurate	1.0	EW	سن	
	Aminocoumarin	.3	EW	-	
	Blue epoxy dispersion	. 7	EW	<i>_</i>	
2	Dibutyltindilaurate	.25	EW		
	Carbon	1.0	EW	- /	
3	Dibutyltindilaurate	1.0	E	W	
	Toluene	18	FW.		
	1,1,1nitrilotri 2 propanol	1	. 2 EW		
	Aluminum oxide	40	EW		
			·		
4					
	Aluminum oxide	38%	EW	٠,٠	

²Use the following codes to designate how the concentration was determined:

A = Analytical result

V = Volume

W = Weight

[_]	Mark (X) t	his	box	if you	attach	а	continuation	sheet.		

E = Engineering judgement/calculation

³Use the following codes to designate how the concentration was measured:

_			٠ ـ ـ ١
Q.	. 05	(cont	inued)

⁵Use the following codes to designate how the concentration was measured:

V = Volume

W = Weight

⁶Specify the analytical test methods used and their detection limits in the table below. Assign a code to each test method used and list those codes in column e.

NΑ Detection Limi: $(\pm ug/1)$ Method Code NA. 1___ NΑ NA_ NA 2 NA_ NA 3_ NA NA NA. NA NA NA

^[] Mark (X) this box if you attach a continuation sheet.

8.06 Characterize each process stream identified in your residual treatment block flow diagram(s). If a residual treatment block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the instructions for further explanation and an example.)

CBI								
[_]	Process	type	wetr	nane 500	cecraf	t coat	ting ma	terial
	a.	b.	c.	d.	е	·	f. Costs for	g.
	Stream ID Code	Waste Description Code	Management Method Code ²	Residual Quantities (kg/yr)		gement dual (%) Off-Site	Off-Site Management (per kg)	Changes in Management Methods
	Taa	B82	<u> </u>	47.6	O	100	\$2.20	none
			NA	NA	NA	<u>NA</u>	NA	NA
			NA	NA	NA	NA	NA	14
			NA	NA	NA	NA	NA	NA
	<u> 166</u>	B82	2I	<	0	100	\$2.20	none
			NA	- NA	NA	NA	_NA	_NA_
			NA	NA	NA	<u>NA</u>	<u>NA</u>	NA
			NA	_NA_	NA	NA_	NA	NA
	NA	NA	NA	<u>NA</u>	NA	_NA_	NA	<u>NA</u>
			NA .	<u>NA</u>	NA	NA	NA	NA
			NA	NA	NA	NA	NA	NA
			<u>NA</u>	NA	NA	NA	_NA	NA
	NA	NA	NA_	NA_	NA	NA	NA	NA
			NA	NA	NA	NA	NA	NA
			NA	NA	NA	NA	NA	NA
		-	NA_	_NA_	NA	NA	<u>NA</u>	NA

¹Use the codes provided in Exhibit 8-1 to designate the waste descriptions ²Use the codes provided in Exhibit 8-2 to designate the management methods

[[]_] Mark (X) this box if you attach a continuation sheet.

WASTE DESCRIPTION CODES

These waste description codes were developed specifically for this survey to supplement the descriptions listed with the RCRA and other waste codes. (These waste description codes are not regulatory definitions.)

WASTE DESCRIPTION CODES FOR HAZARDOUS WASTE DESCRIBED BY A SINGLE RCRA F. K. P. OR U WASTE CODE

AQ1	Spent	Mevice	(F001 ·	F005.	KOB6)	
400	-		ion.	(EOO1.	SOOS.	KORK

A03 Still bottom (F001-F005, K086)

A04 Other organic sludge (F001-F005, K086)

AGS. Wastenation of adulous mixture

ADS Contaminated soil of cleanup residue Other F or K waste, exactly as described ACT7

AOS Concentrated off-spec or discarded

oraduct

A09 Empty containers

"Exactly as described" means that the waste matches the description of the RCRA waste code

A10 Incinerator asn

Solidified treatment residue

Other treatment residue ispecify in A12 Facility Notes 1)

A13 Other untreated waste (specify in Facility Notes")

INORGANIC LIQUIDS-Waste that is onmanly norganic and highly fluid telg., aqueous), with ow suspended inorganic solids and low organic

301 Aqueous waste with low solvents

302 Aqueous waste with low other toxic organics

803 Spent acid with metals

804 Spent acid without metals

905 Acidic aqueous waste

806 Caustic solution with metals but no CVBDIGBS

Causic solution with metals and cyanides

BOS Caustic solution with cyanides but no metals

BO9 Spent causitic

810 Caustic aqueous waste

811 Aqueous waste with reactive sulfides 812 Aqueous waste with other reactives (e.g.,

أعدب والموادعة

B13 Other aqueous waste with high dissolved SOHOS

Other aqueous waste with low dissolved SOLIDS

815 Scrupper water

816 Leachate 817

Waste liquid mercury

818 Other inorganic liquid (specify in "Facility

INORGANIC SLUDGES-Weste that is primarily inorganic, with moderate-to-high w content and low organic content; pumpable.

B19 Lime sludge without metals

820 Lime sludge with metals/metal hydroxide sludge

821 Wastewater treatment studge with toxic organics

822 Other wa towater treatment sludge

823 Untreated planng sludge without cyanides 824 Untreated plating sludge with cyanides

825 Other sludge with cyanides

B26 Sludge with reactive suifides

827 Sludge with other reactives

828 Degreesing sludge with metal scale or filings

B29 Air pollution control device sludge (e.g., fly ash, wet scrubber sludge)

830 Sediment or lagoon dragout contaminated with organics

B31 Sediment or lagoon dragout contaminated with inorganics only

Onlling mud

B33 Aspestos siurry or sludge

834 Chloride or other brine sludge

835 Other inorganic studge (specify in Facility Notes ')

INORGANIC SOLIDS-Waste that is primarily inorganic and solid, with low organic content and low-to-moderate water content; not pumpable.

836 Soil contaminated with organics

A.17 Soil contemporated with inormanics only

838 Ash, sieg, or other residue from incineration of wastes

Other "dry" ash, slag, or thermal 839 readus.

"Dry" lime or metal hydroxide solids 840 chemically "fixed" "Dry" lime or metal hydroxide solids not 841

"fixed" 842 Metal scale, filings, or scrap

843 Empty or crushed metal drums or contauners.

Battenes or battery parts, casings, cores

845 Spent solid filters or adsorbents 846 Ashestos solids and debns

847 Metal-cyanide salts/chemicals

Reactive cyanide salts/chemicals

Reactive suifide saits/chemicals

850 Other mective satis/chemicals

RS1 Other metal salts/chemicals

852 Other waste inordanic chemic

853 Lab packs of old chemicals only

854 Lab packs of debns only

ASS Mixed lab packs

856 Other inorganic solids (specify in Faculty Notes")

INORGANIC GASES—Waste that is primarily ingrounic with a low organic content and is a gas at atmosphene pressure.

857 Inorganic gases

ORGANIC LIQUIDS-Waste that is primarily organic and is highly fluid, with low inorganic solids content and low-to-moderate was content.

858 Concentrated solvent-water solution

859 Halogenated (e.g., chlonnated) solvent

Nonhalogenated solvent

861 Haiopenated/nonhaiogenated solvent mixture

862 Oil-water emulsion or mixture

Weste oil

Concentrated aqueous solution of other 864 organics

Concentrated phenolics

866 Organic paint, ink, lacquer, or varnish

847 Adheaves or expoxies

868 Paint thinner or petroleum distillates

869 Reactive or polymerizable organic liquid

Other organic tiquid (specify in Facility 870 Notes 1

ORGANIC SLLIDGES—Waste that is primarily organic, with low-to-moderate inorganic solids

content and water content; pumpable Still bottoms of halogenated (e.g. chlori-

nated) solvents or other organic liquids 872 Still bottoms of nonnalogenated

solvents or other organic liquids **873** Oily sludge

874 Organic paint or ink studge

875 Reactive or polymerizable organics

876 Resins, tars, or tarry sludge

877 Biological treatment studge

878 Sewage or other untreated biological siudge

879 Other organic studge (specify in Facility Notes")

ORGANIC SOLIDS—Waste that is primarily organic and solid, with low-to-moderate inorganic content and water content; not ритрерів.

840 Halogenated pesticide solid

841 Nonhalogenated pesticide solid

Solid resins or polymenzed organics Spent carbon

Reactive organic solid

Empty fiber or plastic containers Lab pages of old chemicals only

886

Lab packs of debns only

Mixed lab packs

Other halogenated organic solid

Other nonhalogenated organic solid

ORGANIC GASES-Waste that is primarily organic with low-to-moderate inorganic content and is a gas at atmospheric pressure.

891 Organic gases

EXHIBIT 8-2. (continued)

MANAGEMENT METHODS

17VT Ferrous sulfate 18VT Other chromium reduction

Complexed metals treatment (other than chemical precipitation by pH adjustment)
19WT Complexed metals treatment

Emulsion breaking 20WT Thermal 21WT Chemical 22WT Other emulsion breaking

Adsorption
23VT Carbon adsorption
24VT Ion exchange
25VT Resin adsorption
26VT Other adsorption

Stripping 27WT Air stripping 28WT Steam stripping 29WT Other stripping

Evaporation
30VT Thermal
31VT Solar
32VT Vapor recompression
33VT Other evaporation

Filtration
34WT Diatomaceous earth
35WT Sand
36WT Multimedia
37WT Other filtration

Sludge devatering
38VT Gravity thickening
39VT Vacuum filtration
40VT Pressure filtration (belt, plate
and frame, or leaf)
41VT Centrifuge
42VT Other sludge devatering

Air flotation
43VT Dissolved air flotation
44VT Partial aeration
45VT Air dispersion
46VT Other air flotation

Oil skimming 47VT Gravity separation 48VT Coalescing plate separation 49VT Other oil skimming

Other liquid phase separation 50WT Decanting 51WT Other liquid phase separation

Biological treatment
52VT Activated sludge
53VT Fixed film-trickling filter
54VT Fixed film-rotating contactor
55VT Lagoon or basin, aerated
56VT Lagoon, facultative
57VT Anaerobic
58VT Other biological treatment

Other vastewater treatment
59WT Wet air oxidation
60WT Neutralization
61WT Nitrification
62WT Denitrification
63WT Flocculation and/or coagulation
64WT Settling (clarification)
65WT Reverse osmosis
66WT Other wastewater treatment

OTHER VASTE TREATMENT

1TR Other treatment 2TR Other recovery for reuse

ACCUMULATION

1A Containers 2A Tanks

STORAGE

1ST Container (i.e., barrel, drum)
2ST Tank
3ST Waste pile
4ST Surface impoundment
5ST Other storage

DISPOSAL

1D Landfill
2D Land treatment

3D Surface impoundment (to be closed as a landfill)

4D Underground injection well

Chemical precipitation is a treatment operation whereby the pH of a waste is adjusted to the range necessary for removal (precipitation) of contaminants. However, if the pH is adjusted solely to achieve a neutral pH, THE OPERATION SHOULD BE CONSIDERED NEUTRALIZATION (60VT).

)9 <u>I</u>	identified in your	r process block or re	ding POTVs) that manages the residuals sidual treatment block flow diagram(s), and the reporting year. Photocopy this question and te facility.
]	•	Stream ID Code	Annual Quantity (kg)
		aa	less than l
		ъъ	N A
		NA	NA
		NA	NA NA
		NA	NA
		NA	NA NA
		NA	NA
		NA	NA
		NA	NA
		NA	NA
	_		N[E[
			$\left[\frac{\overline{N}}{\overline{S}}\right] \left[\frac{\overline{O}}{\overline{O}}\right] = \left[\frac{\overline{O}}{\overline{S}}\right] = \left[\frac{\overline{O}}{\overline{O}}\right] = \left[$
	EPA Identificatio Hazardous Waste F	n Number (i.e., acility ID Number)	
		·	

Pile	Quantity Managed per Year (cubic meters)	Under Roofed Structure (Y/N)	Type of Contain- ment Provided	Synthetic Liner Base (Y/N) ²	Frequency of Transfer and/or Handling Operations	Stre ID Cod
1	N A	N A	N A	N A	N A	N A
2	NA	NA	<u>NA</u>	NA	NA	<u>NA</u>
3	NA	NA	NA	NA	NA	— NA
4	NA	NA	NA	NA	NA	А
5	NA	NA	NA	NA	NA	NA
No 1 Use the C = Co	following codes mplete (includes	to designat	e the type	of containmen	nt provided:	
1 Use the C = Co co P1 = Pa P2 = Pa N = No	following codes mplete (includes ntainment) rtial-1 (include rtial-2 (include	to designat both dike of s just dike s just under	e the type containment containment ground (lea	of containments and underground) chate) containments	nt provided: und (leachate) inment)	· • • • • • • • • • • • • • • • • • • •
Use the C = Co co P1 = Pa P2 = Pa N = No Vaste m clay la	following codes mplete (includes ntainment) rtial-1 (include) rtial-2 (include) ne ay lie directly yer following codes	to designate both dike of significant the synth	e the type containment ground (lea	of containment and undergrown) chate) contain or the liner	nt provided: und (leachate) inment) may be covered	with a

Stream ID Code	aa	NA	NA	NA	NA
Storage Base Material	В	NA	NA	NA	NA
Maximum Operational Storage Capacity (liters)	3	NA	NA	NA	NA
Average Daily Stored Quantity (liters)		NA	NA	NA	NA
Average Length of Storage (days)	0.6	NA		ı	NA
Treat- nent Types	S	NA	NA	NA	NA
Quantity Stored per Year (liters)	1-2	NA	NA	NA	NA
Design Capacity (liters)	1-2	NA	NA	NA	NA
Container		2	3	4	5

Indicate if Office of Solid Waste survey has been submitted in lieu of response by circling the appropriate response.

_	7
	• •
:	:
:	:
:	÷
•	•
:	:
•	•
:	:
•	•
:	:
:	:
•	•
:	:
•	•
•	•
:	:
:	:
•	•
:	:
•	•
:	:
•	•
:	:
•	•
:	:
•	:
	•
:	:
•	•
:	:
•	•
:	:
•	•
:	:
:	:
•	•
:	:
•	•
•	:
•	•
:	:
:	:
•	•
:	:
•	•
:	:
•	•
:	:
Yes	(No
ě	
>	(3)

Use the following codes to designate storage base materials:

A = Concrete
B = Asphalt
C = Soil
D = Other (specify)

If residual is stored, indicate (Y/N) in parenthesis whether the storage area is designed and operated to collect and contain surface runoff ¹Indicate "S" for storage and use the codes provided in Exhibit 8-3 to designate treatment types

_]		ŊΑ	Average Boiler	Average Fuel Replacement	Stream
	Boiler	Boiler Type ¹	Load ⁴ (%)	Ratio' (%)	ID Code
	1	NA	NA	NA	-NA
	2	NA	NA	NA	NA
	3	NA	NA	NA	NA
	4	NA	NA	NA	_NA
		<u>NA</u>	<u>NA</u>	NA	NA
	No)				
		ring codes to designate			
	¹ Use the follow F = Fire tube W = Water tube ² Designate the	ring codes to designate	boiler type:	l (percent of capac	i ty)
	¹ Use the follow F = Fire tube W = Water tube ² Designate the	ring codes to designate	boiler type:	l (percent of capac	ity)
	¹ Use the follow F = Fire tube W = Water tube ² Designate the	ring codes to designate	boiler type:	l (percent of capac	ity)

Boiler number		N A
		NT A
Stream ID code(s)		NA NA
	Residual, as Fired (or residual mixture if residuals are blended)	Boiler Fuel, as Fir (residual(s) plus primary fuel)
Btu content (J/kg)	NA	NA
Average	NA	NA
Total halogen content (% by	wt.)	
Average	NA	NA
Maximum	NA	NA
	priate response.	tted in lieu of respo
Yes	priate response.	

	Air Pollution	Types of Emissions Data Available
Boiler	Control Device	NA
	N A	
	NA	NA NA
3	N A	NA
4	N A	N A
5	N A	NA .
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:
Use the follo S = Scrubber E = Electrost	wing codes to designate the air pollut (include type of scrubber in parenthes atic precipitator	ion control device:

	your process bit		atment block flow di	NA	
[]	Incinerator	Incinerator Type	Primary Incinerator Fuel ²	Average Fuel Replacement <u>Ratio</u>	Stream ID Code
	1	NA	NA	NA	N A
	2	NA	N A	NA	N A
	3	NA	NA	NA	NA
	Indicate	if Office of Solid	Waste survey has been response.	n submitted in lieu	of respo
	· ·				
	(40)				
	¹ Use the follow	ing codes to design	nate the incinerator	type:	
	1I = Liquid in	jection	6I = Multiple		
	2I = Rotary or	rocking kiln ln with a liquid	7I = Fluidized 8I = Infrared	Dea .	•
	injection		9I = Fume/vapor		
	4I = Two stage		10I = Pyrolytic		
	5I = Fixed hea		11I = Other (spe		
	² Use the follow	ing codes to design	nate the primary inci	inerator fuel:	
	A = Oil	,	D = Wood		
	B = Gas		E = Other (spec	ify)	
	C = Coal Designate the capacity)	percentage of auxi	liary fuel used when	firing residual (po	ercent of
	capacity		•		

[_]		Combustion Chamber Temperature (°C)		Location of Temperature Monitor		Residence Time In Combustion Chamber (seconds)	
	Incinerator	Primary	Secondary	Primary	Secondary	Primary	Secondary
	1	NA	NA	NA_	NA	NA	NA_
	2	NA	NA	NA_	N A	NA	N A
	3	NA	N A	NA	NA	NA_	N A
	by circl	e if Office ling the app	ropriate res	oonse.	s been submit		1
<u>CBI</u>	Incinerator	ck flow diag	Air P	ollution l Device		Type: Emissio	s of
	treatment bloo	ck flow diag	gram(s). Air P <u>Contro</u>	ollution		Type: Emissio	s of ns Data
	treatment bloo	ck flow diag	Air Pontro	ollution l Device		Type: Emissio Avai	s of ns Data
	Incinerator	ck flow diag	Air Pontro	ollution l Device		Type: Emission Avai NA	s of ns Data
	Incinerator 1 2 3 Indicate by circ	e if Office ling the app	Air Portion of Solid Was propriate res	ollution l Device NA NA NA te survey haponse.	as been submi	Type: Emission Avai NA NA NA tted in lieu	s of ns Data lable of response
	Incinerator 1 2 3 Indicat by circ	e if Office	of Solid Was	ollution l Device NA NA NA te survey haponse.		Type: Emission Avai NA NA NA tted in lieu	of response

Incinerator number			NA			
•	Stream ID code(s)					
		Residual, as Fired (or residual mixture if residuals are blended)	Incinerator Fuel as Fired (residual(s) plu primary fuel)			
Btu content (J/kg)						
Average		NA NA	NA			
Minimum		N A	N A			
Feed rate (kg/hr)		N A	N A			
Feed rate (J/hr)(k	g/hr x J/kg)	NA	N A			
Total halogen cont	ent (% by weight)					
Average		N A	NA.			
Maximum		N A	NA			
Total ash content	(% by weight)					
Average		N A	NA			
Maximum		NA	N A			
Total water conten	it (% by weight)					
Average		NA	N A			
Maximum	•	NA	N A			
Indicate if by circling	Office of Solid Was	ste survey has been submitted isponse.	in lieu of respon			
Yes			••••••			
(No)						

8.27 CBI	following table for each dispose of the residual flow diagram(s).	ch on-site land ls identified i	l in a Land Treatment Site treatment site that is us n your process block or re	sidual treatment bloc
[_]			atment	
) <u> </u>	
	Surface water runoff ma	anagement ¹	· · · · · · · · · · · · · · · · · · ·	N A
	by circling the	appropriate res		
	runoff:		the management practices f	
	<pre>A = Collection prior B = Reapplication to</pre>	to treatment the site	<pre>C = Canalization prior D = Other (specify)</pre>	
				•
	•			

On-Site Storage, Treatment, or Disposal in Surface Impoundments -- Complete the following table for the five largest (by volume) surface impoundments that are used on-site to treat, store, or dispose of the residuals identified in your process block or residual treatment block flow diagram(s). CBI

			Stream	ID Code	NA		NA	NA	ΝΑ		NA	
IATE TION	ren	Leachate	Collected	(Y/N)	NA		NA	NA	NA		NA	
LEACHATE COLLECTION	SYSTEM		Installed	(Y/N)	NA		NA	NA	NA		NA	
	LINER		Thickness	(cm)	NA		NA	NA	NA		NA	
	CLAY	No.	oę	Liners	NA		NA	NA	NA		NA	
	IC LINER	Thick-	ness	Liners (cm)	NA		NA	NA	NA		NA	
	SYNTHET	No.	oţ	Liners	NA		NA	NA	NA		NA	
	Average	Residency	Time	(days) ²	NA		NA	NA	NA		NA	
Specify	Disposal or	Treatment	Type if	Applicable 1	ĄN		NA	NA	N A		NA	
		Total	Capacity	(liters)	Ø N		A N	Ϋ́	ΔN	1111	NA	
			Tenonind-	ment	_	-	2	3		3	5	

Indicate if Office of Solid Waste survey has been submitted in lieu of response by circling the appropriate response.

2 Yes (oN)

$$A = Daily$$
 $C = Monthly$ $B = Weekly$ $D = Other (specify)$

Indicate "S" for storage, "D" for disposal, or use the codes provided in Exhibit 8-3 (which follows question 8.13) to designate treatment type

parenthesis using the following codes the frequency with which the impoundment is dredged to clear the residue In addition, indicate in Indicate the residency time for the surface impoundment's flow through stream. that collects on the bottom:

Indicate the thickness of each liner

8.31	State the total	area activ	ely used on-	site for you	r landfill.		
CBI	·						
[_]	Total area activ	ely used .		• • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •		m²
	Indicate i	f Office of	f Solid Wast opriate resp	e survey has	been submits	ed in lieu o	f response
	Yes					• • • • • • • • • •	1
	No		• • • • • • • • • •		••••••	• • • • • • • • • • • • • • • • • • • •	2
8.32 CBI	Complete the fol contain residual diagram(s).	lowing tab s identifi	le for the fed in your p	five largest process block	landfill cell or residual	treatment bl	that ock flow
			KING VER	CAP DE CLAY L			STEM Leachate
	Landfill Cell	Average Use		Installed (Y/N)	Thickness (cm)	Installed (Y/N)	Collected (Y/N)
	1	<u>NA</u>	NA	N A	NA	NA	<u>NA</u>
	22	NA	NA.	NA	N A	<u>NA</u>	<u>NA</u>
	3	NA	N A	NA	NA	N A	<u>NA</u>
	4	NA	NA	NA	NA	NA	NA
	5	<u> </u>	NA	NA	NA	NA	<u>NA</u>
	Indicate by circlin	if Office ong the appr	f Solid Was opriate res	te survey has ponse.	s been submit	ted in lieu o	of response
	Yes						
	No						
	Use the follow: A = Daily B = Weekly C = Monthly D = Other (spec	ing codes t	o designate		use rate:		
[_]	Mark (X) this bo	ox if you a	ittach a con	tinuation she	eet.		

CECTTON	a	VORKER	EXPOSURE

General Instructions	Instructions	:
----------------------	--------------	---

Questions 9.03-9.25 apply only to those processes and workers involved in manufacturing or processing the listed substance. Do not include workers involved in residual waste treatment unless they are involved in this treatment process on a regular basis (i.e., exclude maintenance workers, construction workers, etc.).

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

9.01 Mark (X) the appropriate column to indicate whether your company maintains records on the following data elements for hourly and salaried workers. Specify for each data element the year in which you began maintaining records and the number of years the records for that data element are maintained. (Refer to the instructions for further explanation and an example.)

Data Element	Hourly Workers	intained for Salaried Workers	Data Collection Began	Years Records Are Maintained Medical inder
Date of hire	X	X		medical inder ersonnel 10
Age at hire	<u> </u>	X	11	11
Work history of individual before employment at your facility	Х	X	11	11
Sex	X	X	11	11
Race	X	X	11	11
Job titles	Х	X	11	11
Start date for each job title	X	X	11	- 11
End date for each job title	X	X	11	tt ·
Work area industrial hygiene monitoring data	X	X	1985	Indefinet
Personal employee monitoring data	X	X	1985	
Employee medical history	X	X	1957	11
Employee smoking history	X	X	1957	11
Accident history	Х	X	1957	11
Retirement date	x	Х	1957	11
Termination date	X	X	1957	11
Vital status of retirees	NA	NA_	NA NA	NA
Cause of death data	NA	N A	NA	N A


[[]__] Mark (X) this box if you attach a continuation sheet.

9.02 CBI	In accordance with the in which you engage.	able for each activity			
	a.	b .	c.	d.	e.
	Activit <u>y</u>	Process Category	Yearly Quantity (kg)	Total Workers	Total Worker-Hours
	Manufacture of the	Enclosed	NA	NA	NA
	listed substance	Controlled Release	NA	<u>NA</u>	NA
		0pen	NA	NA	NA NA
	On-site use as	Enclosed	NA	NA	<u>NA</u>
	reactant	Controlled Release	3.0	90	@750
		0pen	NA	NA	NA
	On-site use as	Enclosed	NA	NA	NA
	nonreactant	Controlled Release	NA	NA	NA
		0pen	NA	NA	NA
	On-site preparation of products	Enclosed	NA	NA	NA
		Controlled Release	NA	NA	NA
		Open	NΔ	ΝΔ	NA NA

[[]_] Mark (X) this box if you attach a continuation sheet.

4	In accordance with the indicate associated to	vork a	eas.	115,	provide yo	ur prod		1101 0106	(0)	
Process type Spacecraft urethane coating mixture										
	Process type							operation		
		Note	this	15	exclusiv	ery a	bacch	operation		
					•					
								,		

PROCESS FLOW CHART FOR QUESTION 9.04



ecome in contact with of the exposed and complete it separately for each process type and work area. Spacecraft urethane coating mixture Mix Lab-Controlled clean area											
work area *poter Labor Category	Number of Workers Exposed	re to listed Mode of Exposur (e.g., dire skin contac	substance Physical State of	Average Length of Exposure Per Day	Number of Days per Year Exposed						
1	1	Skin* Air	OL	В	250						
. 2	90	skin Air	OL	A	250						
NA_	NA	N A	N A	NA	N A						
NA_	NA	N A	NA	NA	_NA						
NA	N A	N A	NA	NA.	N A						
N A	NA	N A	NA	NA	N.A.						
N A	N A	N A	N A	N A	N A						
NA_	NA	NA	NA	NA	NA						
NA	.N.A	NA	NA	N.A.	N A						
NA_	NA	N A	NA	N A	N A						
the point GC = Gas temp GU = Gas temp	of exposure: (condensible a erature and produced produce	t ambient essure) at ambient essure;	SY = Sludge or AL = Aqueous 1: OL = Organic 1: IL = Immiscible (specify 90% water	slurry iquid iquid	ubstance a						
A = 15 min B = Greate exceed C = Greate	llowing codes utes or less or than 15 minu ing 1 hour or than one hou ing 2 hours	tes, but not	exceeding	an 2 hours, but 4 hours an 4 hours, but 8 hours	not						

9.08 If you monitor wor	ker exposur	e to the lis	sted substa	nce, compl	ete the fo	llowing table
CBI NA No mon	itoring d	ata availa	able			
[_] Sample/Test	Work Area ID	Testing Frequency (per year)	Number of Samples (per test)	Who Samples ¹	Analyzed In-House (Y/N)	Number of Years Record Maintained
Personal breathing zone	NA	NA	NA	NA	NA	NA
General work area (air)	NA	NA	<u>NA</u>	NA	NA	NA
Wipe samples	NA	NA	<u>NA</u>	NA	NA	NA
Adhesive patches	<u>NA</u>	NA	NA	NA	NA	NA
Blood samples	NA	NA	NA	NA	<u>NA</u>	NA
Urine samples	NA	NA	<u>NA</u>	NA	_NA	NA
Respiratory sample	s <u>NA</u>	NA	NA.	NA	NA	NA
Allergy tests	NA	NA	NA NA	NA	NA	NA
Other (specify)	NA	NA	NA	NA	NA	NA
Other (specify)	NA_	NA	NA	NA	NA	NA
Other (specify)	NA	NA	NA	NA	NA	NA

(⁻ 1	Mark (X) this box if you attach a continuation shee	t.
`		

¹ Use the following codes to designate who takes the monitoring samples:

A = Plant industrial hygienist
B = Insurance carrier
C = OSHA consultant
D = Other (specify)

<u>I</u> _]	Tes	t Description			(weekly,	Frequency monthly, yearly	, etc.)
_	blood work	urinalus	is		annu	1 4	
	annual	Ohusica	I exam	-		7	
		Projecto	4	-			
			· . · · · · · · · · · · · · · · · · · ·	-			
		· · · · · · · · · · · · · · · · · · ·		-			
				•	-		

Describe all equipment or process modifications you have may prior to the reporting year that have resulted in a reduct the listed substance. For each equipment or process modification the percentage reduction in exposure that resulted. Photocomplete it separately for each process type and work area	ification described, stat tocopy this question and		
No Process changes have been made in these areas Process type	NA		
Work area	N A		
Equipment or Process Modification	Reduction in Worker Exposure Per Year (%)		
NA	N A		
NA	NA		
N A	N A		
N A	NA NA		
•			

[] Mark (X) this box if you attach a continuation sheet.

] Proce	NA- No routine use the listed sub				-
Work Area		Average Usage	Fit Tested (Y/N)	Type of Fit Test ²	Frequency of Fit Tests (per year)
N A	NA	NA_	<u>NA</u>	NA_	N A
NA	N A	NA	_NA_	<u>NA</u>	NA
NA	N A	N A	N A	NA	N A
NA	NA	N A	NA	NA .	N A
A = B = C = D = E = 2 Use QL =	the following codes to de Daily Weekly Monthly Once a year Other (specify) the following codes to de Qualitative			st:	
A = B = C = D = E = 2 Use QL =	Daily Weekly Monthly Once a year Other (specify) the following codes to de			st:	
A = B = C = D = E = 2 Use QL =	Daily Weekly Monthly Once a year Other (specify) the following codes to de			st:	
A = B = C = D = E = 2 Use QL =	Daily Weekly Monthly Once a year Other (specify) the following codes to de			st:	
A = B = C = D = E = 2 Use	Daily Weekly Monthly Once a year Other (specify) the following codes to de Qualitative Quantitative		of fit te		
A = B = C = D = E = 2 Use QT =	Daily Weekly Monthly Once a year Other (specify) the following codes to de Qualitative Quantitative	signate the type	of fit te		
A = B = C = D = E = 2 Use QT =	Daily Weekly Monthly Once a year Other (specify) the following codes to de Qualitative Quantitative	signate the type	of fit te		
A = B = C = D = E = 2 Use QT =	Daily Weekly Monthly Once a year Other (specify) the following codes to de Qualitative Quantitative	signate the type	of fit te		

Respirator Maintenance Program For each type of respirator used when working with the listed substance, specify the frequency of the maintenance activity, and the person who performs the maintenance activity. Photocopy this question and complete it separately for each respirator type. NA No routine use of respirators in these areas							
Respirator type							
Respirator	Frequency ¹		Person Performi: Activity				
Maintenance Activity	NA		N A				
Cleaning Inspection	NA		NA				
Replacement							
Cartridge/Canister	NA		NA_				
Respirator unit	ΝA		N A				
A = After each use B = Weekly C = Other (specify) 2 Use the following codes to compare the second s	designate who perform	s the mainter	nance activity:				
B = Weekly C = Other (specify)		s the mainter	nance activity:				
B = Weekly C = Other (specify) 2 Use the following codes to code A = Plant industrial hygien: B = Supervisor C = Foreman		s the mainter	nance activity:				
B = Weekly C = Other (specify) 2 Use the following codes to code A = Plant industrial hygien: B = Supervisor C = Foreman		s the mainter	nance activity:				

a. Respirator ty		routine us	e of respirator	s in these ar	eas
Type of Training	Number of Workers Trained	Location, of	Length of Training (hrs)	Person Performing Training	Pre
N A	NA	N A	N A	N A	
b.					
Respirator ty Type of Re-training	Number of	Location of	Length of Re-Training (hrs)	Person Performing Re-Training	Fre
NA NA	NA	N A	N A	NA	N
E = Emergence R = Routine 2 Use the foll A = Outside	lowing codes lowing codes plant instru	to designate to designate	the type of training		
E = Emergence R = Routine 2 Use the foll A = Outside B = In-house C = On-the-j D = Other (s	Lowing codes Lowing codes plant instruct classroom in the classroom in t	to designate to designate duction instruction	the type of training	aining or re-tra	ining:
E = Emergence R = Routine 2 Use the foll A = Outside B = In-house C = On-the-j D = Other (s	lowing codes plant instruct classroom in the classroom i	to designate to designate duction instruction	the type of traini	aining or re-tra	ining:
E = Emergence R = Routine 2 Use the foll A = Outside B = In-house C = On-the-j D = Other (s) 3 Use the foll re-training: A = Plant in B = Supervis C = Foreman	lowing codes lowing codes plant instruct classroom in the classroom in the classroom in the codes plowing codes industrial hyporomy	to designate to designate designate to designate to designate	the type of training	aining or re-tra	ining:
E = Emergence R = Routine 2 Use the foll A = Outside B = In-house C = On-the-j D = Other (s) 3 Use the foll re-training: A = Plant in B = Supervis C = Foreman D = Other (s)	lowing codes y lowing codes plant instruct classroom in the classroom i	to designate to designate to designate to designate to designate gienist	the type of training the location of training the location of training the person who per	aining or re-tra	ining:

19 <u>I</u>	Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this question and complete it separately for each process type and work area.					
_]	Process type Space	craft urethane c	oating mixtur	е		
	Work area			•		
	Employee training - Chemic	al training. Me	thods designe	d to eliminat	e and	
	minimize any potential exp					
		osure - the irise	<u>ca jabbaanee</u>			
	very small quantities.					
	Indicate (X) how often you leaks or spills of the lis separately for each proces Process type Space	craft urethane c	oating mixtur	`e		
	Process type Space Work area .Due to extreme! spills of thesematerials of	craft urethane of y.small.guantiticontaining the li	coating mixtur es.and method sted substanc 1-2 Times	ts there are rece 3-4 Times	no routine More Than 4	
	Process type Space Work area . Due to extreme! spills of thesematerials of Housekeeping Tasks	craft urethane of y.small.quantiticontaining the linear tess Than Once Per Day	es. and method sted substance 1-2 Times Per Day	there are researce 3-4 Times Per Day	no routine More Than 4	
	Process type Space Work area .Pue.to.extremel spills of thesematerials of Housekeeping Tasks Sweeping	craft urethane of y.small.guantiticontaining the li	coating mixtur es.and method sted substanc 1-2 Times	ts there are rece 3-4 Times	More Than 4	
	Process type Space Work area .Pue.to.extremel spills of thesematerials of Housekeeping Tasks Sweeping Vacuuming	y small quantiticontaining the li Less Than Once Per Day NA NA	es. and method sted substance 1-2 Times Per Day NA	there are researched 3-4 Times Per Day NA	More Than 4 Times Per Da	
	Process type Space Work area .Due to extremel spills of these materials of thousekeeping Tasks Sweeping Vacuuming Water flushing of floors	craft urethane of y.small.quantiticontaining the li Less Than Once Per Day NA NA NA	es.and method sted substance 1-2 Times Per Day NA NA NA	there are reserved. 3-4 Times Per Day NA NA NA	More Than 4 Times Per Da	
	Process type Space Work area .Due to extremel spills of these materials of thousekeeping Tasks Sweeping Vacuuming Water flushing of floors	y small quantiticontaining the li Less Than Once Per Day NA NA	es.and method sted substance 1-2 Times Per Day NA NA NA	there are reserved. 3-4 Times Per Day NA NA NA	More Than 4 Times Per Da	
	Process type Space Work area .Due to extremel spills of these materials of thousekeeping Tasks Sweeping Vacuuming Water flushing of floors	craft urethane of y.small.quantiticontaining the li Less Than Once Per Day NA NA NA	es.and method sted substance 1-2 Times Per Day NA NA NA	there are reserved. 3-4 Times Per Day NA NA NA	More Than A Times Per Da NA NA	
	Process type Space Work area .Due to extremel spills of these materials of thousekeeping Tasks Sweeping Vacuuming Water flushing of floors	craft urethane of y.small.quantiticontaining the li Less Than Once Per Day NA NA NA	es.and method sted substance 1-2 Times Per Day NA NA NA	there are reserved. 3-4 Times Per Day NA NA NA	More Than A Times Per Da NA NA	
	Process type Space Work area .Due to extremel spills of these materials of thousekeeping Tasks Sweeping Vacuuming Water flushing of floors	craft urethane of y.small.quantiticontaining the li Less Than Once Per Day NA NA NA	es.and method sted substance 1-2 Times Per Day NA NA NA	there are reserved. 3-4 Times Per Day NA NA NA	More Than A Times Per Da NA NA	
	Process type Space Work area .Due to extremel spills of these materials of thousekeeping Tasks Sweeping Vacuuming Water flushing of floors	craft urethane of y.small.quantiticontaining the li Less Than Once Per Day NA NA NA	es.and method sted substance 1-2 Times Per Day NA NA NA	there are reserved. 3-4 Times Per Day NA NA NA	More Than Times Per D	

9.21	Do you have a written medical action plan for responding to routine or emergency exposure to the listed substance?
	Routine exposure
	Part of our standard medical treatment plan
	No 2
	Emergency exposure
	Part of our Emergency Medical Response
	No 2
	No
	If yes, where are copies of the plan maintained?
·	Routine exposure: Health office
	Emergency exposure: Health office
9.22	Do you have a written leak and spill cleanup plan that addresses the listed substance? Circle the appropriate response. Yes
	No 2
	Safety/ If yes, where are copies of the plan maintained? Plant Engineering
	Has this plan been coordinated with state or local government response organizations? Circle the appropriate response.
	Yes)
	No
9.23	appropriate response.
	Plant safety specialist . Livia Pontani
	Insurance carrier
	OSHA consultant
	Other (specify)
[-]	Mark (X) this box if you attach a continuation sheet.

9.24	appropriate respon	ise.			cility? Circle the
					2
	OSHA consultant		• • • • • • •		
	Other (specify) _				 4
9.25	response.				Circle the appropriate
					· · · · · · · · · · · · · · · · · · ·
	Consulting physic	ian		• • • • • • • • • • • • • • • • • • • •	 2
					3
	Consulting nurse	• • • • • • •			
	Other (specify) _	Plant	safety	director	
	,				

10.02	is located) in terms of latitude (UTM) coordinates.			
	Latitude		74 .	33 <u>, 38 ,</u>
	Longitude		40 . 1	7.28.
	UTM coordinates Zone	e, Norti	hing, E	asting
10.03	If you monitor meteorological corthe following information.	nditions in the vici	nity of your fac	ility, provide
	Average annual precipitation			inches/year
	Predominant wind direction			N-1-1-1-1
10 04	Indicate the depth to groundwater	r below your facility	y. N/A	
10.04	Depth to groundwater		17.	meters
10.05 CBI	For each on-site activity listed, listed substance to the environme Y, N, and NA.)	, indicate (Y/N/NA) a	all routine rele	ases of the
10.05	For each on-site activity listed, listed substance to the environme Y, N, and NA.)	, indicate (Y/N/NA) a ent. (Refer to the :	all routine rele instructions for vironmental Rele	ases of the a definition of
10.05 CBI	For each on-site activity listed, listed substance to the environme	indicate (Y/N/NA) act. (Refer to the sent.	all routine rele instructions for vironmental Rele Water	ases of the a definition of
10.05 CBI	For each on-site activity listed, listed substance to the environme Y, N, and NA.) On-Site Activity	, indicate (Y/N/NA) a ent. (Refer to the :	all routine rele instructions for vironmental Rele	ases of the a definition of ase Land
10.05 CBI	For each on-site activity listed, listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing	indicate (Y/N/NA) and the control (Refer to the control Environment)	all routine rele instructions for vironmental Rele Water	ases of the a definition of ase Land NA
10.05 CBI	For each on-site activity listed, listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing	indicate (Y/N/NA) and the control (Refer to the control Environment)	all routine rele instructions for vironmental Rele Water NA	ases of the a definition of ase Land NA
10.05 CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing	indicate (Y/N/NA) action (Refer to the sent). Env. Air NA NA	all routine rele instructions for vironmental Rele Vater NA NA	ases of the a definition of ase Land NA NA
10.05 CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used	indicate (Y/N/NA) about. (Refer to the sent. Air Air NA NA Y	all routine rele instructions for vironmental Rele Water NA NA NA	ases of the a definition of ase Land NA NA NA NA
10.05 CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage	indicate (Y/N/NA) and	all routine rele instructions for vironmental Rele Water NA NA NA NA NA	ases of the a definition of ase Land NA NA NA NA NA NA
10.05 CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	indicate (Y/N/NA) and	all routine rele instructions for vironmental Rele Water NA NA NA NA NA NA NA NA NA N	ases of the a definition of ase Land NA NA NA NA NA NA NA NA NA N
10.05 CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	indicate (Y/N/NA) and	all routine rele instructions for vironmental Rele Water NA NA NA NA NA NA NA NA NA N	ases of the a definition of ase Land NA NA NA NA NA NA NA NA NA N

riucess	type			
Proce Strea	1 7 1 1	4		Days o
ID	Media	Average Amount of Listed	Number of	Operat:
Code	Affected ¹	Substance Released	Batches/Year	Year
				•
				-
				-

A = Air B = Land C = Ground D = POT E = Nav F = Non- G = Other	i undwater V igable waterway -navigable waterway er (specify) the average amount o	esignate the media affected: of listed substance released gnate the units used to measu	to the environm	ent and
A = kg/6 $B = kg/6$				

PART B	RELEASE TO	AIR				
10.09 <u>CBI</u> [_]	substance in residual tre source. Do sources (e.g for each pro	terms of a Streament block flo not include raw ., equipment lea cess type.	eam ID Code as id by diagram(s), an material and proaks). Photocopy	entified in your pr d provide a descrip duct storage vents,	tion of each point or fugitive emission omplete it separatel	01
	Point Source			•		
	ID Code			iption of Emission	Point Source	_
	01		<u> </u>	France air all	Vsuanon	
	02		()a	from air gur	1/39/11/92	_
	<u> </u>		NA NA			_
			NA NA			_
	<u>NA</u> NA			75.000		_
	NA NA				and the second s	-
			<u> </u>			_
	NA NA		_NA	-		_
-	<u>NA</u>		NA		·	_
	<u> </u>		<i>\</i> \ <u>A</u>			_
						_

[_] Mark (X) this box if you attach a continuation sheet.

10.11 Stack Parameters -- Identify the stack parameters for each Point Source ID Code identified in question 10.09 by completing the following table.

CBI

[<u>]</u>]	Point Source ID Code	Stack Height(m)	Stack Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building Height(m)	Building Width(m)	Vent Type
•	01	4.2	.3	22	12	4.5	125	<u>H</u>
	N A	NA	N A	NA	NA	<u>NA</u>	<u>NA</u>	N A
	NA	N A	N A	N A	<u>NA</u>	NA	NA_	NA
	NA	N A	N A	N A	N A	N A	NA_	N A
	N A	N A	NA	N A	<u> </u>	NA.	NA	<u>NA</u>
	NA	_NA	NA	NA	NA	NA	NA	_NA
	NA	NA	N A	N A	N A	NA_	NA_	_NA
	N A	N A	N A	NA	NA	N A	NA_	NA.
	N A	NA	NA	NA	NA_	N A	<u>NA</u>	NA
	N A	NA	NA_	NA	NA_	NA	NA	_NA
	NA	N A	NA	NA	NA_	NA.	NA	_N.A

¹Height of attached or adjacent building

H = Horizontal

V = Vertical

²Width of attached or adjacent building

³Use the following codes to designate vent type:

[[]_] Mark (X) this box if you attach a continuation sheet.

Equipment Leaks -- Complete the following table by providing the number of equipment types listed which are exposed to the listed substance and which are in service according to the specified weight percent of the listed substance passing through the component. Do this for each process type identified in your process block or residual treatment block flow diagram(s). Do not include equipment types that are not exposed to the listed substance. If this is a batch or intermittently operated process, give an overall percentage of time per year that the process type is exposed to the listed substance. Photocopy this question and complete it separately for each process type.

Spacecraft urethane coating mixture

Percentage of time per year that the listed substance is exposed to this process

1.0

Number of Components in Service by Weight Percent of Listed Substance in Process Stream Greater Less than 99% 76-99% 26-75% 11-25% than 5% 5-10% Equipment Type Pump seals1 NANΑ NANΑ NANΑ Packed NΑ Х NΑ NΑ NΑ NA Mechanical NΑ NA NΑ NΑ Double mechanical² NΑ NANΑ NA NA Compressor seals NA NA NA NA NA NA NA NΑ Flanges NA **Valves** NΑ NANA NANANΑ Gas³ NA NΑ NANA NΑ NALiquid NA NA NΑ NAPressure relief devices NΑ NΑ (Gas or vapor only) Sample connections NΑ NANANΑ NΑ NΑ Gas NΑ NΑ NA NA NΑ NALiquid Open-ended lines⁵ (e.g., purge, vent) NA NA NANA NA NA" Gas NA ΝA NΑ NΑ NA Liquid

10.13 continued on next page

[] Mark	(X)	this	box	if	you	attach	а	continuation	sheet
----------	-----	------	-----	----	-----	--------	---	--------------	-------

¹List the number of pump and compressor seals, rather than the number of pumps or compressors

Process type ·····	Leak Detection Concentration (ppm or mg/m³) Measured at Inches	- Detection	Frequency of Leak Detection	Initiated (days after	Repairs Complete (days aft initiated
Equipment Type	from Source	<u>Device</u>	(per year)	<u>detection</u>)	Interacto
Pump seals					
Packed _	N A	N A	N A	<u> </u>	<u> </u>
Mechanical	N A	NA	NA_	NA	NA
Double mechanical	NA	NA NA	NA	NA	NA
Compressor seals	N A	NA.	NA_	NA	NA
Flanges	N A	<u>NA</u>	<u>N A</u>	NA	<u>NA</u>
Valves					
Gas .	N A	N A	NA	N A	— NA
Liquid .	NA	NA	N A	NA.	NA
Pressure relief devices (gas or vapor only)	NA	N A	<u>NA</u>	NA NA	N A
Sample connections					
Gas	NA	NA	NA	N A	N A
Liquid	NA	N A	NA	N A	<u>NA</u>
Open-ended lines				•	
Gas	NA	NA	N A	NA	N A
Liquid	N A	NA.	NA	NA	NA
1 Use the following c POVA = Portable org FPM = Fixed point m O = Other (specify)	odes to designate anic vapor analyz onitoring	detection d	levice:		

RELEASE TO WATER								
National Pollutant Discharge Elimination System (NPDES) Discharges Complete the following information for each body of water NPDES discharges are discharged into. If discharges are to more than one body of water, photocopy this question and complete it separately for each discharge.								
Discharge source (stream ID code)		0002534						
response.		_						
Moving body of water		(1)						
Standing body of water	••••••	2						
Estimated average base flow (moving)	UK	1/day						
Estimated average volume (standing)	UK	- ¹						
Average volume of discharge from facility	321,725	1/day						
	365	_days/year						
Maximum volume of discharge from facility	492,050	_ l/day						
•		_ days/year						
Average concentration of listed substance in discharge	0 *	mg/l or ppm						
Maximum concentration of listed substance in discharge	0 *	_ mg/l or ppm						
Publicly Owned Treatment Works (POTW) Complete the following the listed substance which are discharged facility.	wing informa rged to a PO	tion for IW from your						
Discharge source (stream ID code)	• • • • • • • • • •	_ AK						
Average volume of discharge from facility	@378500	_ l/day						
	UK	_ days/year						
Maximum volume of discharge from facility	@529,900	_ l/day						
	UK	_ days/year						
Average concentration of listed substance in discharge	0*	mg/l or ppm						
Mariana concentration of listed substance in discharge	o *	_ mg/l or ppm						
	following information for each body of vater NPDS discharge If discharges are to more than one body of water, photocopy complete it separately for each discharge. Discharge source (stream ID code)	National Pollutant Discharge Elimination System (NPDES) Discharges — Co following information for each body of vater NPDES discharges are discharge to more than one body of vater, photocopy this question complete it separately for each discharge. Discharge source (stream ID code)						

Releases to Soils Complete the following information for up to three random soil core samples that were taken and analyzed for the listed substance during the reporting year. Report the concentrations of the listed substance determined by soil core monitoring studies/tests. Specify the distance from the facility that soil cores were taken, and indicate the soil type and sample depth of the soil cores. (Refer to the glossary for definitions of soil textures given in foo										
NA HO SOIL SAMPLES HAVE DEEN ANALYZED FOR CHE										
Sample	of Listed Substa	ance Distan	ce from	Sample ture Depth (cm)						
1	UK /NA	UK	/NA UK	/NA UK/NA						
2	NA/UK	NA/	JK NA/UK	NA/UK						
3	NA/UK	NA/	JK NA/UK	NA/UK						
OS = On-si Use the fo A = Sand B = Loamy C = Sandy D = Loam	llowing codes to sand loam	G = Sandy clay loa H = Clay loam	.							
samples of analyzed fo	groundwater from r the listed sub substance.	monitoring wells of stance. The average	iuring the reporting	entration refers to						
	Distance from	Well Depth	Concentration (mg/l)	Concentration (mg/l) (± % precision						
Sample				Uk/NA						
	Uk/NA	Uk/NA	UK/NA	UK/NA						
	UK/NA	UK/NA	UK/NA	<u>UK/NA</u>						
boundary:		designate if the s	ample was taken wit	hin the facility's						
_	Sample 1 2 3 *Use the form boundary: OS = On-si *Use the form B = Loamy C = Sandy D = Loam E = Silty F = Silt Releases to samples of analyzed form the listed Sample 1 2 3 *Use the form boundary: *Use the form	soil cores were taken, and cores. (Refer to the gloss note 2.) NA no Concentration (note is before the content of the content of the substance. 1	soil cores were taken, and indicate the soil to cores. (Refer to the glossary for definitions note 2.) NA no soil samples have of Listed Substance Sample (± % precision) 1	soil cores were taken, and indicate the soil type and sample depicores. (Refer to the glossary for definitions of soil textures gnote 2.) NA no soil samples have been analyzed Concentration (ug/kg) listed substance of Listed Substance Distance from Plant (m) Soil Tex 1 UK /NA UK/NA UK/NA UK/NA UK/NA 1 UK /NA UK/NA UK/NA NA/UK NA/UK NA/UK NA/UK NA/UK NA/UK NA/UK NA/UK NA/UK NA/UK 1 Use the following code to designate if the sample was taken with boundary: OS = On-site 2 Use the following codes to designate soil texture: A = Sand G = Sandy clay loam B = Loamy sand H = Clay loam C = Sandy loam I = Silty clay loam D = Loam J = Sandy clay E = Silty loam K = Silty clay F = Silt L = Clay Releases to Groundwater Complete the following information for samples of groundwater from monitoring wells during the reporting analyzed for the listed substance. The average and maximum concentration from Depth (mg/l) Sample Plant (m) (m) (± % precision) 1 UK/NA UK/NA UK/NA UK/NA 2 UK/NA UK/NA UK/NA UK/NA 1 Use the following code to designate if the sample, was taken with boundary:						

PART E NON-ROUTINE RELEASES

10.23	Indicate the date and time when the release occurred and when the release c was stopped. If there were more than six releases, attach a continuation s	eased or heet and
	lier all releases.	

Release	No nonroutine Date Started	releases of the Time (am/pm)	nis compound Date Stopped	Time (am/pm)
1	NA	NA	N A	NA
	NA	NA	<u>NA</u>	<u>NA</u>
3	N A	<u> </u>	NA NA	NA
5				
6	-			

10.24 Specify the weather conditions at the time of each release.

Release	Wind Speed (km/hr)	Wind Direction	Humidity (%)	Temperature (°C)	Precipitation (Y/N)
11	NA	NA	NA_	NA	N A
2	NA	N A	NA	N A	N A
3	NA	N A	NA	N A	NA NA
4	N A	N A	NA_	NA	N A
5	NA	NA	NA	N A	N A
6	N A	NA_	<u>NA</u>	N A	N A

 Mark	(X)	this	box	if	you	attach	a	continuation	sheet
 UGIK	(4)	CHIS	007		, 00	a	_		•

release.	N A	
Release No	NA NA	·····
Cause of Release		
Equipment failure		
Operator error	NA	. 2
Bypass condition		
Upset condition		
Fire		
Unknown		
Other (specify)		
Results of Release		
Spill	NA	1
Vapor release		
Explosion		
Fire		
Other (specify)		

[[]_] Mark (X) this box if you attach a continuation sheet.

	(continued)						
	c. Local	_	UTINE RE				
	Agency	[_1]					
	Office	[_]					
	Contact Pe	rson [₁ ₁ ₁ _	_1_1_1_1_1_1			
				-,-,-,-,-,-,			
		(_1_1_1				_1_1_1_1	1_1_1_1_1
		•			·		[<u>]</u>
	Telephone	Number		[
							Day Year
	Time Notif	fied	, 		, 	(_)_]_]]] am/pm
10.29			ties listed	below, indicate	whether th	e hohararr	~·· · -·· -
	who notified that and time of date	the populat ay the evac	tion, the rought on beg	number of people of gan.	evacuated,	if any, an	
	who notified that and time of date	the populat ay the evac	tion, the rought on beg	or, or evacuated number of people (evacuated,	if any, an	d the date
	who notified that and time of date	the popular ay the evac Notified of	tion, the rought on beg	number of people of gan.	Area Evacuated	if any, an	
	who notified to and time of da Release No Proximity to	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified and time of dand time of dand Release No Proximity to the Release	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified to and time of do Release No Proximity to the Release 1/4 mile	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified to and time of do Release No Proximity to the Release 1/4 mile 1/2 mile	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified and time of dand t	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified and time of dand t	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified and time of dand t	the popular ay the evac Notified of Release	tion, the fountion beg	number of people of gan. Notifying Person's	Area Evacuated	if any, an Number of Persons	Date and Time of Day Evacuation
	who notified and time of dand t	Notified of Release (Y/N)	Notifying Person	number of people of gan. Notifying Person's	Area Evacuated (Y/N)	if any, an Number of Persons	Date and Time of Day Evacuation

	Indicate which of the prevention practices and policies listed in question 10.32 were ineffective in preventing the release from reaching the environment.								
	Release No. NO NON-ROUTINE RELEASES.								
. 34	Describe all repairs and/or preventive measures (management practices, operational changes, etc.) made to equipment or operations as a result of the release.								
	Release No								
. 35									
. 35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.								
. 35	Describe additional preventive measures that will be taken to minimize the								
. 35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.								
. 35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence. Release No								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence. Release No								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence. Release No								
.35	Describe additional preventive measures that will be taken to minimize the possibilities of recurrence. Release No								

MORTON THIOKOL, INC.

Morton Chemical Division



Material Safety Data Sheet

SECTION I:	PRODUCT IDENTIFICATION	
PRODUCT NAME: CHEMICAL NAME: COMMON NAME: CAS NUMBER: PRODUCT USE:	S-113 Isocyanate Terminated Polyol Isocyanate Terminated Polyol None Coatings and Castings	1.76

815-338-1800 (24 hours/day) EMERGENCY PHONE:

312-807-3142 OTHER EMERGENCY PHONE: December, 1987 EFFECTIVE DATE: SUPERSEDES: October 15, 1986

HAZARDOUS INGREDIENTS SECTION II:

ACCIH/TLV OSHA CHEMICAL NAME/COMMON NAME CAS NO. PEL 2 TWA STEL Toluene Diisocyanate TDI 584-84-9 0.02ppm 0.005ppm 0.02ppm

1 Typical amount, not a specification

2 Governed by a ceiling limit value (c) - The value which should not be exceeded even instantaneously.

SECTION III: PHYSICAL DATA 482 degrees F (250 degrees C) BOILING POINT (760 mm Hg): SPECIFIC GRAVITY (Water = 1): 1.073 VAPOR PRESSURE (mm Hg): Not applicable -VAPOR DENSITY (Air=1): > 6 93 % NONVOLATILE: Not applicable :Hq EVAPORATION RATE (Ether=1): < 1 SOLUBILITY IN WATER: Not applicable APPEARANCE: Pale Yellow Irritating Pungent Odor ODOR:

SECTION IV: FIRE AND EXPLOSION DATA

FLAMMABLE LIMITS Lel: Not Applicable FLASH POINT: > 200 degrees F (> 94 degrees C) <u>Uel:</u> Not Applicable

METHOD USED: SETAFLASH

EXTINGUISHING MEDIA: Foam, dry chemical.

SPECIAL FIRE FIGHTING PROCEDURES: Fire fighters should wear NIOSH/MSHA approved self-contained positive pressure breathing apparatus.

UNUSUAL FIRE AND EXPLOSION HAZARDS: None as far as known.

HAZARDOUS DECOMPOSITION PRODUCTS: If burned, gives off carbon monoxide, carbon dioxide, nitrogen oxides, aromatic amines, aldehydes, and hydrogen cyanide.

ORAL TOXICITY: Unknown for product mixture. Animal experiments indicate that the toxic effects of TDI or polymeric isocyanates, when ingested, are slight. The ID50 in rats for TDI is 5840mg/Kg. From these experiments, it is believed that ingestion of TDI or polymeric isocyanates would not be fatal to humans, but could result in irritation and corrosive action on the mouth and stomach tissue. See 3

<u>DERMAL TOXICITY:</u> Unknown for product mixture. Isocyanates react with skin protein and tissue moisture. If not promptly removed, liquid spills on the skin can cause reddening, swelling, and blistering of exposed skin. REPEATED SKIN CONTACT HAS CAUSED SKIN SENSITIZATION IN HUMANS AND SHOULD BE AVOIDED.

TDI: Skin-Rabbit: 500 mg/24H MOD See Note 3

EYE TOXICITY: Unknown for product mixture. EYE CONTACT - LIQUID ISOCYANATES SPIASHED INTO THE EYES CAN BE HARMFUL TO THE DELICATE EYE TISSUE AND MUST BE AVOIDED. Injury results from reaction of the isocyanate with the eye fluid which may dehydrate the tissue and result in severe irritation of the eyelid and possible damage to the cornea (corneal opacity). Exposure to high concentrations of isocyanate vapor can lead to formation of solid crystals in the eye fluid causing mechanical irritation of the eyes hours after exposure. TDI Eye-Rabbit: 100 mg SEV See Note 3

INHALATION TOXICITY: Unknown for product mixture. Inhalation of isocyanate vapors can produce severe irritation of the mucous membranes in the respiratory tract, i.e. nose, throat, and lungs. Exposure of humans to concentrations of isocyanate vapor in excess of the maximum acceptable concentration has caused illness characterized by breathlessness, chest discomfort and reduced pulmonary function. Massive exposure to high concentrations has caused, within minutes, irritation of the trachea and larynx and severe coughing spasms. Massive exposure may also lead to bronchitis, bronchial spasm, and/or pulmonary edema (chemical pheumonitis). Concentrations of isocyanate vapors should be maintained below the TLV by engineering controls. Can cause sensitization in humans.

TDI Inhalation-Human TCLO: 0.02 ppm/2Y:PUL See Note 3 TDI Inhalation-Human TCLO: 0.5 ppm:IRR See Note 3

CHRONIC TOXICITY: Unknown for product mixture. Toluene Diisocyanate (TDI) is considered a suspect carcinogen as tested by National Toxicology Program, 1983, in rats and female mice. Administered by gavage to rats, TDI caused subcutaneous neoplasms or cancers in both sexes. Additionally, males developed pancreatic neoplasms and females pancreatic, liver and mammary neoplasms. In mice similarly exposed, TDI caused circulatory neoplasms and cancers (combined) and liver neoplasms in females but was not carcinogenic to males. (NTP 1983 Program Tech Report on Carcinogenic Study of Commercial Grade of TDI.)

EFFECTS OF OVEREXPOSURE:

INGESTION:

Not established for product mixture. Possible nausea, vomiting, and gastrointestinal pain.

SKIN CONTACT:

Not established for product mixture. May cause irritation, dermatitis and possible skin sensitization given prolonged or repeated skin contact.

3 R.T.E.C.S. 1981-82 CZ6300000

EYE CONTACT:

Not established for product mixture. Possible

irritation, tearing, reddening and blurred

vision.

INHALATION:

Not established for product mixture. Possible

respiratory tract, mucous membrane

irritation, sensitization. Symptoms may be delayed and could include dry cough, chest tightness, wheezing, shortness of breath,

asthmatic type symptoms.

ACUTE SYSTEMIC:

Overexposure may cause irritation of the eyes, nose and throat. Severe overexposure

may cause weakness, drowsiness, and

unconsciousness.

CHRONIC SYSTEMIC:

Signs and symptoms from chronic exposure resemble those from acute mishaps but are in

part systemically more severe. Extended

exposure to isocyanates can cause

sensitization resulting in asthmatic type

symptoms.

NOTES: Toxicity testing on the product mixture has not been conducted.

Comments listed in HEALTH HAZARD DATA pertain to the isocyanate listed in HAZARDOUS INGREDIENTS.

MEDICAL CONDITIONS GENERALLY RECOGNIZED AS BEING AGGRAVATED BY EXPOSURE:

Persons with preexisting skin disorders may be more susceptible to
isocyanate. In persons with impaired pulmonary function, especially
those with obstructive airway diseases, the breathing of isocyanate
vapors may cause exacerbation of symptoms due to irritant properties
of the isocyanate.

SECTION VI: EMERGENCY HEALTH AND FIRST AID PROCEDURES .

- EYE CONTACT: Immediately flush with water for 15 minutes lifting the upper and lower eyelids occasionally and obtain immediate medical attention.
- SKIN CONTACT: Remove contaminated clothing. Wash exposed areas thoroughly with soap and water. Wash contaminated clothing thoroughly before reuse. If irritation is present after washing, get medical attention.
- <u>INHALATION:</u> Move to an area with fresh air and free from risk of further exposure. Administer artificial respiration as required. Obtain medical attention.
- <u>INGESTION:</u> Do not induce vomiting. Obtain immediate medical attention. If unavailable, contact nearest Poison Control Center.
- NOTE TO PHYSICIAN: May cause weakness, drowsiness, unconsciousness, irritation of eyes, nose and throat, nausea, possible sensitization, coughing, tightness of chest (TDI). No known antidote. Supportive therapy is recommended. Careful lavage may be indicted after ingestion.

SECTION VII:

REACTIVITY DATA

STABILITY: Stable under ordinary storage conditions.

HAZARDOUS CONDITIONS TO AVOID: Storage at temperatures above 110 degrees F (43 degrees C) and moisture contact.

INCOMPATIBILITY: (MATERIALS TO AVOID) Oxidizing substances.

CAN HAZARDOUS POLYMERIZATION OCCUR: No.

HAZARDOUS DECOMPOSITION PRODUCTS AND CONDITIONS: If burned, gives off carbon monoxide, carbon dioxide, nitrogen oxides, aromatic amines, aldehydes, and hydrogen cyanide.

SECTION VIII:

SPILL OR LEAK PROCEDURES

RESPONSE TO SPILLS: Stop discharge and contain spill or contaminated material using dike, barrier or other means. Recover with pumping equipment, vacuum truck, sorbent vermiculite or other means. Place contaminated material in suitable container(s) for further handling.

HAZARDS TO BE AVOIDED: Do not flush into stream, other bodies of water or storm sewer. Avoid contact with skin or clothing. Other hazards see Section IV FIRE AND EXPLOSION DATA and Section V HEALTH HAZARD DATA. SPILL NOTIFICATION: Check Federal and State reporting regulations.

DISPOSAL METHODS:

- 1 Recycle if feasible.
- 2 Incinerate at authorized facility.
- 3 Treatment at industrial or liquid treatment facility.
- 4 Landfill after solidification in a facility authorized to receive waste.

NOTE: THIS MATERIAL, IF BEING DISCARDED, SHOULD BE DISPOSED OF IN ACCORDANCE WITH LOCAL, STATE, AND FEDERAL REGULATIONS.

SECTION IX:

CONTROL MEASURES

- <u>RESPIRATORY PROTECTION:</u> Wear NIOSH-MSHA approved self-contained positive pressure breathing apparatus as necessary within equipment limitations. Comply with OSHA 1910.134 (CFR), respiratory protection. Contaminant levels will vary dependent on the operation. Industrial hygiene consultation is recommended to assist in respirator selection, use and training.
- FOR HANDS, BODY: Chemical resistant gloves recommended for hand protection, work clothing for general body protection.
- FOR EYES: Wear safety glasses, chemical goggles or face shield (eight inch minimum).
- <u>VENTILATION:</u> Provide adequate ventilation to minimize inhalation.

 Mechanical (local exhaust) recommended for all spray operations and elevated temperature uses.

SECTION X:

SPECIAL PRECAUTIONS

RECOMMENDED STORAGE PRACTICE AND CONDITIONS: Store between 50 and 100 degrees F (10 and 38 degrees C). Storage at higher temperatures causes polymerization.

OTHER PRECAUTIONS: For industrial use only. Eye wash and shower should be available. Use only under well ventilated conditions. For personal hygiene protection, personnel should wash thoroughly after handling product. Always wash up before eating, smoking, or using washroom facilities. Do not breathe vapor. Do not contact eyes, skin, and or clothing.

SECTION XI:

LABELING INFORMATION

DOT SHIPPING NAME:

Not regulated by DOT

DOT IDENTIFICATION NO.:

Not applicable

DOT LABEL:

Not applicable

MORTON PRECAUTIONARY LABEL: 177

Τ,,

SECTION XII:

USER'S RESPONSIBILITY

A bulletin such as this cannot be expected to cover all possible situations. As the user has the responsibility to provide a safe workplace, all aspects of an individual operation should be examined to determine if, or where, precautions in addition to those described herein, are required. Any health hazard and safety information contained herein should be passed on to your customers or employees, as the case may be. Morton Thiokol, Inc. must rely on the user to utilize the information we have supplied to develop work practice guidelines and employee instructional programs for the individual operation.

DISCLAIMER OF LIABILITY

The information contained herein is, to the best of our knowledge and belief, accurate. However, since the conditions of handling and use are beyond our control we make no guarantee of results, and assume no liability for damages incurred by use of this material. All chemicals may present unknown health hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards which exist. Final determination of suitability of the chemical is the sole responsibility of the user. Users of any chemical should satisfy themselves that the conditions and methods of use assure that the chemical is used safely. NO REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS OR IMPLIED, OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR ANY OTHER NATURE ARE MADE HEREUNDER WITH RESPECT TO THE INFORMATION CONTAINED HEREIN OR THE CHEMICAL TO WHICH THE INFORMATION REFERS. It is the responsibility of the user to comply with all applicable federal, state, and local laws and regulations.

Nothing contained herein is to be construed as a recommendation for use in violation of any patents or of applicable laws or regulations.

Morton Thiokol, Inc. Morton Chemical Division 333 West Wacker Drive Chicago, Illinois 60606-1292 (312) 807-2000